Inspection: Chemical Storage Assessment - University of Massachusetts - Amherst

Inspection date: 12/07/2011, time: Tech: Fugere Alesia

Site: EH&S/117 Draper Hall -

Building: Morrill Science Center Section I

Department: **Public Health**Principal Investigator: **Hanchett** 

Safety Officer:

Room: N253 Location: Entire Area

Score: 100% Rating: Good

Follow-up Status: None

Question			
1	Bottles are bar-coded	Yes.	
2	Bottles are labeled properly	Yes.	
3	Containers are in good condition	Yes.	
4	Chemicals stored appropriately and by compatibility	Yes.	
5	Hazardous liquids are stored below eye level	Yes.	
6	Liquid Nitrogen/Cryogenics present	N/A	
7	Acid/Base bath in use	N/A	
8	Peroxide formers are dated	N/A	

Comments:

Follow-up:



Triumvirate Environmental Advise System.

Inspection: Equipment Assessment - University of Massachusetts - Amherst

Inspection date: 12/07/2011, time: Tech: Fugere Alesia

Site: EH&S/117 Draper Hall -

Building: Morrill Science Center Section I

Department: **Public Health**Principal Investigator: **Hanchett** 

Safety Officer:

Room: N253 Location: Entire Area

Score: 100% Rating: Good

Follow-up Status: None

Question		Answer
1	Are Gas cylinders secured with straps/chains without excessive ganging? (no more than 6)	Yes.
2	Cylinders are labeled, caps are on, not blocking means of egress	Yes.
3	Chemical Hood #s	
4	Chemical hood inspection date	
5	Chemical hoods are clean/clutter free	N/A
6	Refrigerators are present and free of spills	N/A
7	Freezers are free of ice buildup and are free of spills	N/A
8	Autoclave is available for decontamination of biowaste	N/A
9	Vacuum pumps have a guard and no excess oil	N/A
10	Microwave ovens and ice machines are "For Lab Use Only"	N/A
11	Bunsen Burner hoses are in good condition	N/A
12	Centrifuges have containment vessels in use (caps, sealed rotors)	N/A
13	Lasers are present	N/A

Comments:

Follow-up:



Triumvirate Environmental Advise System.